ALERT: 26-MCPE - ROUTINE MX EVENT

WANTED

Eddy current inspection of wing to fuselage fittings

Item Id: WWDMA

Testing & Certification - Embraer E190 - EHAM

Item Description

Perform eddy current and detailed visual inspection of wing to fuselage attach fittings per the C-check task cards, with signed reports.

Item Details

PART / IPC REFERENCE **Not specified**	ALTERNATE PART NUMBERS **Not specified**
QUANTITY **Not specified**	REQUIRED ONSITE **14OCT26 0600Z**
REVISION **Not specified**	MANUFACTURER **Not specified**
MANUFACTURER TYPES **Not specified**	ACCEPTABLE MANUFACTURERS **Not specified**
AIRCRAFT MANUFACTURER **Not specified**	AIRCRAFT MODEL **Embraer E190**
ENGINE MANUFACTURER **Not specified**	ENGINE MODEL **CF34-10**
ATA 100 CHAPTERS 57 Wings	CONDITION **SV**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**
TRANSACTION TYPES **Not specified**	INCOTERM **Not specified**
ONSITE LOCATION TYPE **Hangar / Maintenance Facility**	SERVICE AREA **Not specified**
LEAD TIME **Not specified**	EXPORT READY **Not specified**
WARRANTY **Not specified**	WARRANTY TERMS **Not specified**